

egal Description:

te North 1/2 of the SE 1/4 and South 1/2 of the NE 1/4 of Section 30, Township 14 South, Range P.M., Situate in the City of Colorado Springs, County of El Paso, State of Colorado, more ed as tolibras: Beginning at the Wiscomer of Lort, 1 Block 15, Stration Meadows Subdivision No. Ital Book U at Page 20 in the records the El Paso County Clerk and Recorder; thence the sea are field measurements; thence, 1) SSC553375 et along the Southwesterly line of stad Block 28, 10 feet; thence (2) S41*51137E along the Southwesterly line of stad Block 15, a distance of 28, 21 feet; thence, (3) Nort-4507W, a distance of 678.21 feet; thence (4) S70*207CW, a distance of 678.21 feet; thence the Sasterly R.D.W. Inte of Southgate Road; thence, (5) Northwesterly for stad Easterly R.D.W. to the left, said curve haring a radius of 771.54 feet, a cernial angle of 25*0547; an arc they find the safety R.D.W. The a distance of 450.65 feet to the South line of Lymn Avenue as platted adows Subdivision No. 2; thence (7) N62*1125*E along said South line of Lynn Avenue a

of the 6th P.M., in the City of Colorado Springs,

A portion of the Northeast Quarter, Section 30, Township 14 South, Range 66 West

El Paso County, State of Colorado

Surveyor's Statement:
The undersigned Registered Land Surveyor in the State of Colorado hereby certifies to Archon Financial, L.P. and its successors and/or assigns, Commonwealth Land Title Insurance Company, as follows:

- This map or plat and Survey on which it is based were made in accordance with, and meets the requirement of the "Minimum Standard Detail Requirements for ALTACSML Land Tills Surveys" jointly established and adopted by the American land Tille Association and the American Congress on Surveying established and happing the American land Tille Association and the American Congress on Surveying and 989 and meets the accuracy requirements for a Casos. Under one survey was made on the ground between April 4, and April 2, 2003, by men Survey as supervision and correctly shows the area of the subject properly, the location, size and type of all buildings structures and other improvements (including sidewalks, curbs, tences and overhead utility thens) shade on the subject properly, including all setback and yard lines, and any other matters shuated on the subject properly.
- s buildings, structures and improvements shown constitute all of the improvements on said property and are within the boundary line of property, except as noted.

- The record description of the subject property forms mathematically closed figure. There are no easements or rights of way which are visible or of which the undersigned has been advised, ucept as shown.
- are no party walls and no observable abuse ground encreachments (a) by Improvements on additional or or alleys unperforments on additional properties, steel or alley, or (b) by Improvements on additional properties, or alleys unperforment or any assertion and the steel or alleys of the steel or alleys of the steel or alleys and the steel or alleys are steel or alleys of the steel or alleys are steel or alleys or a steel or alleys or al
- Subject has access to and from a duly dedicated and accepted public street or highway as shown
- Utilities (water.gas.electric, and sewer) are available and service the Property. All utility lines enter the avantiess though adjoining public streets or through apparent easements of record which are shown on the Survey as platted streets.
- his ALTA Land Survey Plat does not constitute a title search by ALESSI and ASSOCIATES, Inc. to televimine womership of easements of record. For all information regarding easements, flight-of-Way and title of Record, ALESSI and ASSOCIATES, Inc. referred to Commonwealth Land Title Insurance company, Commitment No. 401182 dated March 20, 2003 at 7:30 A.M.
- survey measurements were made in accordance with the "Minimun Angle, Distance and Closure items for Survey Measurements which control Land Boundaries for ALTA/ACSM Land Title
- A portion of this site is withinkins shown based on map interpolation in designated F.E.M.A. Floodplain as determined by the Flood bisurance allea Map. Community Panel Number 0804 C073FF, effective March 17, 1997. The structures divellings are tool located within the designated Floodplain based upon map interpolations and Elevation Certificates (attached). Field investigation of elevation grades indicated that the flood plain is confined to the concrete channel located at the South boundary.

Joseph Alessi, PLS Colorado Registered No 30130

_day of ______, 2003 A.D. at ____O'Clock in Book ____ of the County Surveyor's Land Survey Plat/Right of Way Surveys at page ___, this Land Survey Plat compiles with Section

Deputy Clerk and Recorder

a additional facts that an accurate and correct title search and/or lied to, descriptions contained in deed for adjacent properties. This than the parties certified to in the Surveyors Statement, contain all of the information obtained or developed by the surveyor

of Bearing as Shown, ment, undefined as per Book 3833 at Page 58.
**sement along the Southerly boundary inclusive of a concrete drainage

a) Apparent easement along the Southerly boundary inclusive of a concrete drainage of amendation of the control of the control

Access is permitted onto Lynn Avenue and Southgate Road. Lot Size = 10.29 Acres

must commence any legal action based upon any defect in this survey within three ch defect. In no event may, any action based upon any defect in this survey be is from the date of certification shown hereon.

ALESSI and ASSOCIATES, Inc. APPRAISERS • ENGINEERS • SURVEYORS

Tele. 719/540-8832 Fax 719/540-2781

Township 14 South, Range 66 West,

Job No. 03-1351 ALTA Survey Plat DATE April 14, 200